

Snow Foam Lance



Professional foamer.



Properties:

- High foaming performance with **ACTIVE SHAMPOO 3000**
- Solid brass body of the foamer
- Highly durable stainless injector and foam nozzle
- Extra strong HDPE bottle, 1000 ml volume
- Low weight
- Easy connection to a hand held high-pressure spray gun

Advantages:

- Forms rich “wet” foam
- Flexible application nozzle for variable spraying width
- Variable adjustment of water to **ACTIVE SHAMPOO 3000** ratio
- Practical markings on the bottle for precise concentrate dilution
- Using adapters, it is compatible with most brands of high-pressure spray guns

Applications:

SNOW FOAM LANCE is a professional foamer used with **ACTIVE SHAMPOO 3000** to form and apply thick, wet foam. Rich foaming ensures the foam's adhesion to any surface. With the appropriate adapter, **SNOW FOAM LANCE** can be attached to high-pressure spray guns of most power washer manufacturers. Thanks to high foaming performance and low weight, it can be used to apply foam not only on personal and commercial vehicles but also on motorcycles, agriculture, construction or gardening machinery and more. Variable setting of spraying width helps achieve high application performance.

Order codes:

Name	Storage code	Package	Volume / Size	Order number
Snow Foam Lance	SFL	Box	1 pc	R 34150

Instructions for use:

- Connect the appropriate adapter based on your high-pressure spray gun and seal the joint with the attached Teflon tape
- Unscrew the bottle and slide the suction hose onto the foamer
- Pour the desired amount of **ACTIVE SHAMPOO 300** into the bottle
- Top up the bottle with water - use warm water for best performance
- Screw the bottle back on the foamer and shake well
- Attach **SNOW FOAM LANCE** to a high-pressure spray gun
- Apply thick wet foam
- During application, adjust the water to foam ratio with the top turning valve or adjust the foam spraying width with the front nozzle
- After application, rinse the bottle thoroughly and wash all **SNOW FOAM LANCE** components

ACTIVE SHAMPOO 3000 consumption is directly proportional to the set foam to water ratio.

Tips:

- For best washing result, use warm water of maximum 60 °C for the high-pressure washer.
- Always apply foam in stripes from the bottom up with a 1/3 overlap of individual foam layers. Leave for two minutes and rinse well with clean water using a high-pressure washer.
- First rinse in full stripes from the bottom up and afterwards from top to bottom for the final rinse.

Technical data:

Colour:	Dark blue
Bottle volume:	1000 ml
Maximum water temperature:	60 °C
Maximum pressure:	160 Bar
Adapter connection thread pitch diameter:	Internal ¼ inch
Injector and foam nozzle material:	Stainless steel

Storage:

Store at a temperature between 0 °C and 35 °C.

Declaration:

The information and recommendations in this publication are to the best of our knowledge reliable. However nothing herein is to be construed as a warranty or representation. Users should make their own tests to determine the applicability of such information or the suitability of any products for their own particular purposes. Statements concerning the use of the products described herein are not to be construed as recommending the infringement of any patent and no liability for infringement arising out of any such use is to be assumed.

Address:

RETECH, s.r.o., Vackova 1541/4; Praha 5 - Stodůlky; Czech Republic

Contact address: 285 02 Suchdol u Kutné Hory cp. 212; tel./fax: +420 327 596 128; e-mail: info@retech.cz